

INSPEÇÃO DE AVALIAÇÃO — ADVANCED — NME ROUND BALER INSPECTION

2013 John Deere 569 Premium

Inventário: A22-26A

Série: 1E00569DEDD390377

Garantia desconhecida

LOCAL DE ARMAZENAGEM

Nelson Motors & Equipment / 731753

Radville, SK, S0C 2G0

Contato:

FOTOS (0 Total)

RESUMO

Estado geral:
Comentários
gerais:
Horas:

								Custo estimado		
	EXCELENTE	BOM	MEDIANO	RAZOAVEL	RUIM	N/A	Observações	Peças	Mão-de-obra	Total
Transmissão		X						0	0	0
Frame and Wheels			X					0	0	0
Twine and Wrap System			X					0	0	0
Pickup		X						0	0	0
Belts		X						0	0	0
Bale Tensioning System		X						0	0	0
Sistemas Elétricos		X						0	0	0
Equipamento de Segurança								0	0	0
Miscelâneos								0	0	0
Overall Machine Rating								0	0	0

TRANSMISSÃO

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Condition of Drive Sprockets and Chains		X					Not hooked.			
Condition of Shields		X					All there and not beat up			
Condition of Universal Joints		X								
Condition of Slip Clutch		X					Cam cut out. Not slip clutch. No damage			
Condition of Gear Box		X					Ethan just re-sealed			

FRAME AND WHEELS

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Condition of Sheet Metal		X					Excellent. Shedded.			
Condition of Tires			X				One main tire has a gouge but holds air fine. One pickup wheel is split and needs replacing			
Condition of Frame/Hitch? Any Cracks or Welds ☐ Sim ☐ Não							No welds on frame or hitch			

TWINE AND WRAP SYSTEM

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Twine arms, Cylinders, Hoses and Cutter		X								
Drive Belt, Pulley, Rollers and Knife			X				Small weld near brake.			

PICKUP

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Condition of Strippers		X								
Condition of Gauge Wheels		X								
Condition of Pick-up Teeth Are there broken and damaged Teeth ☐ Sim ☐ Não		X								
Condition of Auger and Rotor Feed System Are there broken or damaged Knifes ☐ Sim ☐ Não							Pickup is in good shape visibly.			
Condition of Roller Baffle and Forming shield		X								

BELTS

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Condition of Forming Belts - how much tread is remaining.		X					Just below 2 bars			
Belt Tracking Guide		X								
Condition of Splices/Pins		X					All new pins and 7 of 8 lacing just replaced.			
Condition of Roller Bearings		X					Look good not sure if any will be needing replaced.			

BALE TENSIONING SYSTEM

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Tensioning Cylinders and Hoses		X					No leaks			
Condition of Tensioning Springs and Gate Latches		X					None broken or cracked.			

SISTEMAS ELÉTRICOS

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Monitor and Harness Present and Functioning		X					No monitor			
Lights and Warning Lights Operate		X					Assuming they work			

EQUIPAMENTO DE SEGURANÇA

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Are all Safety Shields, Covers and Shrouds Present X Sim ☐ Não										
Is there an Operator's Manual Present X Sim ☐ Não										
Is SMV Safety Decals Present X Sim ☐ Não										

MISCELÂNEOS

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Any Other Features or Notable Concerns										

OVERALL MACHINE RATING

								Custo estimado		
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A				
							Observações	Peças	Mão-de-obra	Total
On a Scale of 1-10						8				