

INSPEÇÃO DE AVALIAÇÃO — ADVANCED — BRANDT ARTICULATED 4WD

2024 John Deere 9R 490

Inventário: 695117

Série: 1RW9490DJRA085911

Garantia desconhecida

LOCAL DE ARMAZENAGEM

Kibble Equipment / 088537

SLEEPY EYE, MN, 56085

Contato:

FOTOS (0 Total)

RESUMO

Estado geral:
Comentários
gerais:
Horas:

								Custo estimado		
	E X C E L L E N T E	B O M	M E D I A N O	R A Z O A V E L	R U I M	N / A	Observações	Peças	Mão-de-obra	Total
brandt articulated 4wd								0	0	0
Avaialbility Date/Hours								0	0	0
Transmission								0	0	0
SUSPENSION-PIVOT								0	0	0
TIRES								0	0	0
PTO/3POINT/STEERING								0	0	0
HYDRAULICS								0	0	0
WEIGHTS								0	0	0
GENERAL NOTES								0	0	0
PHOTOS- minimum required pictures for evaluation								0	0	0
BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-								0	0	0
Pricing								0	0	0

Stock Number: 695117

Model: 9R 490 Serial Number: 1RW9490DJRA085911

BRANDT ARTICULATED 4WD

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Did you start and operate the machine? ☐ Sim ☒ Não										
Has this machine had a power chip? ☐ Sim ☒ Não										
Has the factory equipped DEF system been removed? ☐ Sim ☒ Não										

AVAILABILITY DATE/HOURS

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
WHAT IS YOUR ANTICIPATED AVAILABILITY DATE FOR THIS ITEM? WHAT IS THE MM/DD/YY THIS WILL BE READY TO DELIVER TO THE NEXT BUYER?							✓ What is your anticipated availability date for this item? When will it be on the lot ready to deliver to the next buyer? 12-20-25			
PLEASE BE SPECIFIC ABOUT CURRENT ENGINE HOURS AND WHAT THEY WILL BE WHEN AVAILABLE FOR RESALE							✓ PLEASE BE SPECIFIC ABOUT CURRENT ENGINE HOURS AND WHAT THEY WILL BE WHEN AVAILABLE FOR RESALE Expecting 500 hrs Dec. '25			

TRANSMISSION

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Transmission type							✓ E18			

SUSPENSION-PIVOT

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
DOES THIS HAVE HYDRACUSHION?							✓ YES			
DOES THIS HAVE A HEAVY DUTY GUDGEON BEARING?							✓ YES			

TIRES

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
TIRE SIZE							✓ 710/70R42			
TYPE							✓ DUALS			
TREAD REMAINING Take pictures of face to show stubble damage and sides to show cuts and tears							✓ 80%			

PTO/3POINT/STEERING

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
							✓ 3 POINT HITCH			
Rock Box							✓ No Rock Box			

HYDRAULICS

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
							✓ 5SCV			

WEIGHTS

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
FRONT WEIGHTS IN LBS# TAKE PICTURE OF FRONT WEIGHTS							Front Weight Support w/ 36 weights 4375 lbs			
REAR WEIGHTS IN LBS# TAKE PICTURE OF REAR WEIGHTS							pair of starter wheel weights front and rear 3 pair- 452lb weights front 3 pair - 452 weights rear 3030 lbs total wheel weights			

GENERAL NOTES

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
OVERALL NOTES ON UNIT										

PHOTOS- MINIMUM REQUIRED PICTURES FOR EVALUATION

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
DO YOU HAVE PICTURES OF?										

BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Each section must be completed or it will be returned-							✓ Each section must be completed or it will be returned-			
My expected broken items cost and description							✓ No Broken Items			
My missing items replacement cost and description							✓ No missing items			
My expected leaking items cost and description							✓ No leaking items			
My expected safety items cost and description							✓ No safety items to fix			
My expected Service costs and description (Example:oil-fluids-filters-wash)							✓ Cost and description of oil-fluids-filters and wash and to put on front line-enter in notes \$775 - Inspection Kibble Ready Plus \$6,000.00 BLMSS and service \$750.00 Wash \$7525.00			

PRICING

							Custo estimado			
	NOVO	BOM	UTILIZAVEL	REPARAR	SUBSTITUIR	N/A	Observações	Peças	Mão-de-obra	Total
Total BMLSS cost (must be broken down in section above)							✓ Total BMLSS cost (must be broken down in section above) \$7525.00			
My Expected Sale Price							\$507000.00			